







LVT



Mannington
COMMERCIAL

| Installation Method | Products | Advantages | Disadvantages |
|--|---|--|---|
|  <p>Traditional Glue Down</p> | <p>Amtico Signature, Amtico Anthology, Amtico Northern Wonder, Connected, The Drift Collection, The Portland Project, Access, Cirro, Spacia, Infused, Spacia First 20, Spacia First, Divergent, Mannington Select, Color Anchor, Nature's Paths, Primary Elements, Walkway 20, Walkway</p> | <ul style="list-style-type: none"> • Most versatile and common method • High performance method • Safest method for most commercial applications | <ul style="list-style-type: none"> • Requires proper preparation • Separate adhesive cost • Time for adhesive to set up • Moisture tolerances (specific to each adhesive) |
|  <p>Pre-applied Adhesive</p> | <p>Amtico Signature QuickStix, Amtico Anthology QuickStix, Amtico Northern Wonder QuickStix, Connected QuickStix, The Drift Collection QuickStix, The Portland Project QuickStix, Spacia QuickStix, Infused QuickStix, Divergent QuickStix, Mannington Select QuickStix, Color Anchor QuickStix, Nature's Paths QuickStix, Primary Elements QuickStix</p> | <ul style="list-style-type: none"> • Highest performance system • Goes over some existing floors • Moisture tolerances • No set up time | <ul style="list-style-type: none"> • Higher price point • Additional lead times • Requires prime coat |
|  <p>Click</p> | <p>City Park, Mannington Crown Collection</p> | <ul style="list-style-type: none"> • Goes over existing subfloors • Superior sound abatement • No set up time • Cleaner install | <ul style="list-style-type: none"> • No heavy rolling loads • Requires technically sound installation • Expansion gaps required |
|  <p>Tackifier Adhesive/ Loose Lay</p> | <p>Access</p> | <ul style="list-style-type: none"> • Sound abatement built in • Some methods allow for access to subfloor • Thickness similar to carpet for seamless installs | <ul style="list-style-type: none"> • No heavy rolling loads • Mold and mildew under and between product • Higher cost per square foot |